

Fitch Family Indoor Aquatic Center Monthly Project Status Report March 2025

PROGRESS THIS PAST MONTH:


- 1. Roofing was completed on the Natatorium.
- 2. Fire sprinkler piping and ductwork has been installed in the ceiling of the Natatorium.
- 3. Precast concrete in the areas of the building outside of the Natatorium has been completed.
- 4. Main structural steel installation has been completed outside of the Natatorium, with detailing nearing completion.
- 5. Special inspections and testing of structural steel and base-of-precast grout continued and are ongoing.
- 6. Roofing operations began on the lower roof area.
- 7. Joint sealant work related to the precast concrete panels has been ongoing.
- 8. Pre-Install meetings were held for pre-wiring rough-ins and pools and concrete slab vapor barrier.
- 9. Submittals and Requests for Information continued to be processed between the Bid Package Contractors, Story Construction, and RDG Planning & Design.

WORK PLANNED FOR NEXT MONTH:

- 1. Installation of fire sprinkler piping, ductwork, and electrical conduit in the ceiling of the Natatorium is planned for completion.
- 2. Painting of the ceiling in the Natatorium.
- 3. Wellness pool basin work is starting.
- 4. Structural steel detailing for the area of the building outside of the Natatorium is scheduled for completion.
- 5. Roofing is scheduled for completion in the area outside of the Natatorium.
- 6. Removing frost from the subgrade and drying the dirt inside of the building as the roofing is completed.
- 7. Underground plumbing is planned to begin in the area outside of the Natatorium.
- 8. Joint sealant work will continue at the joints between the precast concrete wall panels, including the Building Envelope Consult inspections for this work.
- 9. Development of the Crew Workflow Plan for the site improvements such as storm sewer, grading, and parking lot paving.

SCHEDULE SUMMARY:

Construction Substantial Completion Date: January 20, 2026





PROJECT PHOTOS:

Progress

North Elevation showing structural steel for roof top equipment screening

Taken Date 03/14/2025 at 12:16 pm

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name Exterior Elev View South...



Progress

SW Elevation - Temporary enclosure at future glazing, and temp heat at future water slide opening

03/14/2025 at 12:10 pm

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name West Ext temp opening ...







Progress

South wall of Wellness pool high ceiling mechanical rough ins

Taken Date 03/14/2025 at 12:08 pm

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name Wellness high ceiling rou...



Progress

View to Southeast showing high ceiling mechanical rough ins

Taken Date 03/14/2025 at 12:08 pm

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name Nat view east high ceilin...







Progress

View from top end of walking track showing clerestory glazing openings and completed roof deck

03/14/2025 at 12:00 pm

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name North Walk Track view to...



Progress

North elevation of curtain wall glazing showing walking track space

Taken Date 03/14/2025 at 11:57 am

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name Walk Track joists & decki...







Progress

North Main Entry showing metal framing for future metal panel finishes

Taken Date 03/14/2025 at 11:56 am

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name Main entry framing.jpg



Progress


View looking east of locker rooms with roofing and roof drains in progress


Taken Date 03/14/2025 at 11:54 am

Upload Date 03/16/2025 at 10:57 am

Uploaded By Deb Thurmond

File Name Locker Room Roofing & ...







Progress

View East over locker rooms showing roof curbs for future roof top units

Taken Date 03/03/2025 at 03:00 pm

Upload Date 03/07/2025 at 02:28 pm

Uploaded By Eli Rochleau

File Name 2B83073D-A18B-4D13-8...



Progress

Northwest Natatorium roof showing completed membrane roofing

Taken Date 03/13/2025 at 02:49 pm

Upload Date 03/17/2025 at 03:14 pm

Uploaded By Deb Thurmond

File Name 20250313_144926.jpg

